

Thank You for contacting ThunderMax product support.

How to Initialize a Thunder Max Module- (all versions)

- Turn key to 'ON' position for 20 seconds.
- Turn key to 'OFF' position for 20 seconds.
- Repeat key on / off 20 seconds, process 3 times.
- Upon completion of the *Key Cycle*, Turn key to 'ON' position and start engine.
- Allow engine to run until it reaches normal operating temperature.

It is **VERY** important that when performing this cycle, the key remains in the 'ON' and 'OFF' position for a full 20 Seconds.

If after completing the *Key Cycle* the bike is running poorly, immediately shut engine off for one minute and repeat the process from the beginning.