

Missing Vacuum Cap

How to inspect for a Missing Vacuum Cap:

1. Approach the RIGHT side of the motorcycle
2. Using a light, look under the tank at the Air Cleaner location, on top of the Throttle Body
3. It is hard to see and sets back in between the cylinders, on top of the Throttle Body
4. There is a ¼" steel vacuum tube
5. This steel vacuum tube should have a rubber cap on it
6. Verify the rubber cap is in place
7. If the rubber cap is missing, it must be replaced

Note: Refer to "Map - Reloading Your Base Map" if the cap is found to be missing.

NOTE: Auto parts stores will have rubber vacuum caps OR you can use a short piece of vacuum hose with a small bolt in the end (acting as a plug). The "hose and bolt" arrangement is actually more secure than the rubber caps. A little ugly but does not show.

